



## TECHNICAL DATASHEET

<b>Code</b>	IND-U6S
<b>Brief Description</b>	Humidity indicators, box of 250
<b>Type</b>	Spot 6
<b>Dimensions outer</b>	105 x 37 h mm
<b>Package</b>	of 250 pieces



### Description

Humidity indicators

Humidity indicators signal when a specified relative humidity is exceeded.

Signaling is done by changing the spots from brown to light blue.

- They signal the level of humidity present from 10% to 60%.
- They do not contain cobalt.
- Place the indicators inside the packages.